

THERMOGRAPHIC REPORT

Company Tremblay Electricque

Problem #

IDENTIFICATION


Location Name Room D-003, pump B004-EF

Equipment B004-EF starter

PROBLEM DESCRIPTION

One fuse (right) is rated at 20 amps while the others are 30 amps

THERMOGRAM



TEMPERATURE MEASUREMENTS

Image Date	25/05/2005 3:17:10 PM
Target Temperature	45.5 °C
Emissivity	0.85
Reflected Temp	OFF

WEATHER

Air Temp	na
Sky	na
Wind Speed	na
From	na

Distance	Rated Load	Meas. Load	% Load
na	na	na	na

MAINTENANCE ACTION

Description	Repaired by
Ensure fuses are properly installed and rated.	

REPAIR PRIORITY

Subj. Rating	high
Temp. Rating	

REINSPECTION

Reinspected by	
Date	



Comments

Ensure fuses are properly installed and rated.